Please note that in case you have version 1.3 or older versions, you must install first version 1.4 and only then version 2.0

Improvements / changes of version 2.0
DAS240

Main improvements:

➢ Improvement of the display of temperature measurements
➢ Resolution for Pt100-Pt1000 is now 0.1°C
➢ Improvement of data buffer management

Minor bugs correction

Improvements / changes of version 1.7
DAS240

Main improvements:

➢ TCP commands added
➢ New WiFi driver added
➢ Compatibility with LabVIEW driver

Minor bugs correction

Improvements / changes of version 1.5
DAS240

Main improvements:

➢ Alarm status is added in the status bar.
➢ Improvement of standard deviation calculation
➢ Channel increment added in the math calculation window
➢ Math calculation between cursors has been added
➢ Improvement of Pt100 3 wires with long integration period
➢ Web Services added and the download of files when recording is authorized

Minor bugs correction

This firmware update is fully compatible with **DAS240**

If you want to be informed of software releases and new products introduction, please follow-us on Twitter : @SEFRAM_SAS