

| >> Thermocouple | TK 2000 | TK 2002 |
|--------------------|---|--|
| Sensor used | K thermocouple | |
| No. of inputs | 1 | 2 |
| Measurement range | -50 °C to 1,000 °C | |
| Resolution | 0.1 or 1 °C | |
| Accuracy | -50 °C to 0 °C: ± 1 °C / 0 to 1,000 °C : $\pm 1.5\%$ ± 0.5 °C | |
| Functions | | |
| Hold | YES | |
| Measurement unit | °C | |
| Display | 2,000 counts | |
| Dimensions | 63 x 163 x 37.5 mm | |
| Weight | 200 g | |
| Delivery condition | with 1 flexible K thermocouple sensor for measurements from -40 °C to +200 °C | with 2 flexible K thermocouple sensors for measurements from -40 °C to +200 °C |